Taylor Made Design & Build

Email: tpruittdemos@uda1.com

515 W Avenue - December 29, 2016

Phone: (800) 700-8321 x 380 • Fax: (334) 821-0815

515 W Avenue Seattle, WA 98103

2060 Sage Court

Auburn, AL 36830

Client(s): Jenny Cartwright, Jack Franklin

Punch Lists > Closeout Punchlist

1. Countertop is cracked near the left side of the range Countertop needs to be replaced before we move on to other items. Due: 12/30/16 Priority: High Status: None Assigned Resource(s): Ian Schaefer, Taylor Pruitt Room/Location: None

Issues:

Contact supplier to schedule material delivery

Disconnect gas and remove range

Install countertop and replace range

2. Door into master bedroom opens outward instead of inward

Due:1/3/17Priority:NoneStatus:NoneAssigned Resource(s):Taylor PruittRoom / Location:None

□ 3. Dining room chandelier does not turn on

Due:NonePriority:NoneAssigned Resource(s):NoneRoom / Location:None

Issues:

Call electrician to rewire

Check circuit to ensure other lights on the breaker are working

4. Tapestries for the living room have not arrived

Once they arrive, double check the size and material and then install Due: None Priority: None Status: None Assigned Resource(s): Ian Schaefer Room / Location: None

5. Paint is chipped in the hallway connecting the living room and guest bedroom

Repaint. Spare paint should still be in the utility closet on the back patio.

Due:NonePriority:NoneStatus:NoneAssigned Resource(s):Taylor PruittRoom / Location:None

6. Flood lights are not correct - should be automatic sensors

Due:NonePriority:NoneAssigned Resource(s):Brad SandersonRoom / Location:None

Issues:

Verify exact unit homeowner would like

Price check local vendors and pick up lights in store

Install lights

7. Connect Washer and Dryer

Due:NonePriority:NoneAssigned Resource(s):Ian SchaeferRoom/Location:None

Completion Approval

Contractor's signature

Owner's Signature

Date

Date